Low Volume Vehicle Technical Association (inc)

SAFETY ALERT INDEX

Part 7 – Volume 5 September 2025

Helping New Zealanders Build & Modify Safe Vehicles

Doc #	Subject	Issue date	Issue status
01-2025	Unisteer-brand Welded Steering Rack and Pinion	April 2025	current
03-2024	Superformance-brand Lower Control Arm Failure	September 2024	current
02-2024	1958 -1964 Chevrolet Y-Bone Track Locator Arm	August 2024	current
01-2024	MPW-Brand Triumph Daytona Lower Linkage Arm	August 2024	current
02-2023	Aftermarket Tubular Suspension Arms with Cantilever-style Ball Joints	June 2023	current
01-2023	Copies of 'Astro Supreme'-Brand Wheels	June 2023	current
02-2022	Steering Arm Failures - OEM Early Ford V8 Passenger Car (1932 – 1948)	April 2022	current
01-2022	Motorcycle Handlebar Failure - Unsafe Aftermarket Handlebars	April 2022	current
09-2021	Sub-Standard Aftermarket Cast-Iron I-Beam Axles 'Helix'-brand supplied by 'Johnny Law Motors'	October 2021	current
08-2021	'TCI"-Brand Aftermarket One Piece Dropped Spindles (Stub Axles)	September 2021	current
07-2021	Multi-Piece Aftermarket Suspension Arms Including "SPC Performance' and 'Stiffler'-brands	September 2021	current
06-2021	Motorcycle Wheel Failures "Motea Gmbh Craftride'-brand	September 2021	current
05-2021	So-Cal-Brand Forged 5-Inch Dropped I-Beam Axles	September 2021	current
04-2021	Twin Beam Dropped Axle Failures DJM/LCM Truck-brand "Dream Beam'	September 2021	current
03-2021	Unsafe Aftermarket Wheel Nuts	June 2021	current
02-2021	Aftermarket Chrome Brake Booster Bolt Failure	June 2021	current
01-2021	'Magnum Force'-Brand Aftermarket Dropped Spindles (Stub Axles)	June 2021	current
10-2020	Faulty Threads on Aftermarket Suspension Arms	December 2020	current
09-2020	'Heidts'-brand Suspension Arm Issue	December 2020	current
08-2020	Rear Suspension Failure – Graham Berry/Kiwi Race Cars AC Cobra Replica	December 2020	current
07-2020	Steering Rack Spacers	December 2020	current
06-2020	Multi-piece HICAS Lock-bars	December 2020	current
05-2020	Y32 and Y33 Nissan Strut Warning	December 2020	current
04-2020	Sub-standard Suspension Arms	September 2020	current
03-2020	MBM-brand Disc Brake Kits	September 2020	current
02-2020	Machined-down Brake Calipers (for wheel clearance)	September 2020	current
01-2020	EPMAN-brand Harness Seatbelts	September 2020	current
06-2019	CPP-brand Welded Aftermarket Pitman Arm Failures	September 2020	current
05-2019	Aftermarket Cast I-beam Axle Failures	September 2020	current
04-2019	'Superbell'-brand Ductile Cast Iron Spring Perch Bolts	May 2019	current
03-2019	'Superbell'-brand Ductile Cast Iron Spindles	May 2019	current
02-2019	APV Seatbelt Bolt Recall	February 2019	current
01-2019	Strut Spacers and Ball-joint Spacers	January 2019	current
12-2018	'TCI'- brand Independent Front Suspension Failure	December 2018	current
11-2018	Counterfeit Steering Wheels and Quick Release Boss Kits	November 2018	current
10-2018	Non-compliant Aftermarket Seat Belts	October 2018	current
09-2018	Modified 'Borgeson'-brand Steering Boxes	September 2018	current
08-2018	Tri-5 Chevrolet Power Steering Rack Kit	September 2018	current

07-2018	Failed Steering Column Support Brackets	September 2018	current
06-2018	Kit Car Steering Column Shafts	September 2018	current
05-2018	Aftermarket Brake Booster	September 2018	current
04-2018	Counterfeit Full-harness Seatbelts	September 2018	current
03-2018	Aluminium Wheels Nuts	September 2018	current
02-2018	'CPP'-brand Steering Couplers	September 2018	current
01-2018	Tie-rod End 'Extenders' for Bump-steer Reduction	September 2018	current

Note: - shading indicates new or revised documents included with this index from previous issue.